## OFED Bugs open as of 11/20/2016

| | Sev | Pri | OS | OFED | Assignee | Summary | Opened | 11/06/16 | 11/20/16 | Change | Issue | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 2561 | nor | P5 | SL 7.0 | 3.18-2 | erezsh@mellanox.com | IPoIB failure after arp cache flush. | 07/20/15 | REOP | REOP | No | IPoIB | Rupert re-assigned to Erez on 4/25/2016 |
| 2583 | maj | P5 | RHEL 7.1 | 3.18-2 | tatyana.e.nikolova@intel.com | iwpm_mapping_error_cb: Received msg seq = 381240 err code = 12 client = 3" seen intermittently | 12/29/15 | ASSI | ASSI | No | iwpm | Steve: Veeresh please try with the latest upstream kernel as per tatyana's request. We want to verify its fixed upstream. Pinged 5/23 and 6/2 We'll have to live with this in OFED-3.18. |
| 2587 | enh | P5 | SLES 11 SP4 | 3.18-2 | sean.hefty@intel.com | autoconf is needed by ibacm-1.1.0-1.x86_64 | 02/05/16 | ASSI | ASSI | No | ibacm | Arlin: provided a patch to eliminate the autoconf dependency. May be fixed - bug needs updating and verifying |
| 2598 | Nor | P5 | RHEL 6.6 | 3.18-2 | vlad@mellanox.co.il | Failed to build libibverbs RPM with OFED-3.18-2-20160515-0319 daily build on RHEL6.6 | 05/16/16 | New | New | No | libibverbs | Steve: OFED distro should have its own spec files that disable rpath as suggested by Doug Ledford |
| 2600 | Blo | P5 | CentOS 6.4 | 3.18-2 | vlad@mellanox.co.il | 3.18-1 + 3.18-2-rc2 fail compat-rdma build due to bad structs | 05/19/16 | New | New | No | compat-rdma | Vlad needs to review: This build works for kernel 3.18.27, but bombs on 3.18.33 from kernel.org. |
| 2602 | Cri | P5 | RHEL 6.6 | 3.18-2 | sthun@ddn.com | RHEL 6.6 crashed during Switch-to-controller cable pull less than failover | 06/24/16 | New | New | No | SRP | |
| 2603 | nor | P5 | All | 3.18-2 | amir.hanania@intel.com | dtest -D does not work with "ofa-v2-scif0-u" provider | 08/15/16 | New | New | No | DAPL | |
| 2605 | enh | P5 | All | 3.18 | sean.hefty@intel.com | prov/acmp/src/acmp.c: 2 * bad width ? | 09/02/16 | New | New | No | ibacm | |
| 2606 | nor | P5 | All | 3.18-2 | amir.hanania@intel.com | dtestcm server delays for long time on startup | 09/08/16 | New | New | No | DAPL | |
| 2607 | maj | P5 | All | gen2 | sean.hefty@intel.com | rmda_client and rdma_server send/recv/cmpl sequence | 09/08/16 | New | New | No | RDMA CM | |
| 2609 | enh | P5 | Other | Other | dean.luick@intel.com | qperf.c:2057: possible &/&& muxup | 10/14/16 | New | New | No | qperf | |
| 2611 | blo | P5 | RHEL 7.2 | 4.8 | vlad@mellanox.co.il | Latest 4.8 snapshot does not work with mlx5 card (MT27600) | 11/14/16 | New | New | No | mlx5 | |
| | | | | | | | | | | | | |

| | |
|---|---|
| nor | 4 |
| blo | 2 |
| cri | 1 |
| maj | 2 |
| min | 0 |
| enh | 3 |
| Total | 12 |

| | |
|---|---|
| ASSI | 2 |
| FIXED | 0 |
| Invalid | 0 |
| LATER | 0 |
| NEW | 9 |
| REOP | 1 |
| WONTFIX | 0 |
| WORKS | 0 |
| Total | 12 |