OFED Bugs open as of 11/06/2016										Comments		
	Sev	Pri	os	OFED	Assignee	Summary	Opened	09/12/16	11/06/16	Change	Issue	
2561	nor	P5	SL 7.0	3.18-2	erezsh@mellanox.com	IPolB failure after arp cache flush.	07/20/15	REOP	REOP	No	IPoIB	Rupert re-assigned to Erez on 4/25/2016
<u>2583</u>	maj	P5	RHEL 7.1	3.18-2	tatyana.e.nikolova@intel.com	iwpm_mapping_error_cb: Received msg seq = 381240 err code = 12 client = 3" seen intermittently	12/29/15	ASSI	ASSI	No	iwpm	Steve: Veeresh please try with the latest upstream kernel as per tatyana's request. We want to verify its fixed upstream. Pinged 5/23 and 6/2 We'll have to live with this in OFED-3.18.
<u>2587</u>	enh	P5	SLES 11 SP4	3.18-2	sean.hefty@intel.com	autoconf is needed by ibacm-1.1.0-1.x86_64	02/05/16	ASSI	ASSI	No	ibacm	Arlin: provided a patch to eliminate the autoconf dependency. May be fixed - bug needs updating and verifying
<u>2598</u>	Nor	P5	RHEL 6.6	3.18-2	vlad@mellanox.co.il	Failed to build libibverbs RPM with OFED-3.18-2-20160515-0319 daily build on RHEL6.6	05/16/16	New	New	No	libibverbs	Steve: OFED distro should have its own spec files that disable rpath as suggested by Doug Ledford
<u>2600</u>	Blo	P5	CentOS 6.4	3.18-2	vlad@mellanox.co.il	3.18-1 + 3.18-2-rc2 fail compat-rdma build due to bad structs	05/19/16	New	New	No	compat-rdma	Vlad needs to review: This build works for kernel 3.18.27, but bombs on 3.18.33 from kernel.org.
2602	Cri	P5	RHEL 6.6	3.18-2	sthun@ddn.com	RHEL 6.6 crashed during Switch-to-controller cable pull less than failover	06/24/16	New	New	No	SRP	
<u>2603</u>	nor	P5	All	3.18-2	amir.hanania@intel.com	dtest -D does not work with "ofa-v2-scif0-u" provider	08/15/16	New	New	No	DAPL	
<u>2604</u>	enh	P5	All	3.18-2	amir.hanania@intel.com	Don't run atomic tests on hardware that does not support it	08/26/16	New	Fixed	Yes	DAPL	Fixed in latest dapl git. 1/10/2016
<u>2605</u>	enh	P5	All	3.18	sean.hefty@intel.com	prov/acmp/src/acmp.c: 2 * bad width ?	09/02/16	New	New	No	ibacm	
2606	nor	P5	All	3.18-2	amir.hanania@intel.com	dtestcm server delays for long time on startup	09/08/16	New	New	No	DAPL	
2607	maj	P5	All	gen2	sean.hefty@intel.com	rmda_client and rdma_server send/recv/cmpl sequence	09/08/16	New	New	No	RDMA CM	
<u>2608</u>	min	P5	Other	Other	hal@mellanox.com	2 * redundant code	09/09/16	New	Fixed	Yes	OpenSm	
<u>2609</u>	enh	P5	Other	Other	dean.luick@intel.com	qperf.c:2057: possible &/&& muxup	10/14/16	New	New	No	qperf	
2608	blo	P5	RHEL 6.7	4.8	vlad@mellanox.co.il	Failed to build compat-rdma RPM on RHEL 6.7 with OFED 4.8	11/05/16	New	Invalid	Yes	Installer	OFED 4.8 has not been ported to RHEL 6.7

	nor	4				
	blo	2				
	cri	1				
	maj	2				
	min	1				
	enh	4				
	Total	14				

ASSI	2
FIXED	2
Invalid	1
LATER	0
NEW	8
REOP	1
WONTFIX	0
WORKS	0
Total	14